ps (restricted day	(ASS)	VEGOS),	
يهور			· · · · · · · · · · · · · · · · · · ·
	ar ^a	ow.	.,
		2 July 1963	
REPLY TO ATTN OF:	P. E.	2 0025	•
SUBJECT:	Monthly Activities Report for June	1963	
TO:	Commander WRSP-IV	1	
	1. Flight Discrepancies: There w	ere no personal equipment	discrepancies
	noted through-out the reporting pe	riod.	
STATINTL		ctrinated the Squadron Co	
	the use of high altitude personal	equipment. The Commander	has been
·	fitted with a partial pressure sui	t and helmet for use in s	ubsequent
STATINTL	flight training. had	accomplished training in	pre-breath-
	ing preparations and assisted in	· · · · · · · · · · · · · · · · · · ·	
ف	progressing slowly due to duty rec	uirements requiring immed	iate attention.
STATINEL	3. TDY's: TDY to Laug	hlin AFB and Barksdale AF training	B from 22 to
4	28 June to provide technical super	visory and/support for Ba	ASS KNOB.
STATINTL	4. leaves: took le	ive from 10 to 20 June.	
	5. Seat Pack Maintenance: In ad	lition to routine seat pac	k maintenance,
STATINTL	serviced three (3) ARDC	seat packs.	
	6. Equipment and Material: Tran	sportation: The medical/	Personal Equip-
	ment section has been assigned a	Chevrolet staff car and a	Pontiac ambulance
	to meet the units transportation	requirements. The ambular	nce is being
	considered to eventually replace	the P.E. transport truck	as the primary.
	transfer vehicle. The P.E. truck	will be used as a back u	p transfer
	vehicle and for TDY's.		
STATINTL	Partial Pressure Suits:	has had opportunit	y to thoroughly
	Approved For Release 2002/06/24 check out his modified partial pr	ESIA-RDRISERIOSERIO 020	0100028-80 him.

XERO

STATINT

A new one has been requisitioned for him and, upon receipt of the new suit, his present back up suit will be returned to David Clark for reconditioning and alterations.

new suit has been determined to be acceptable and a requisition has been submitted for an additional suit. Upon receipt of the second suit, his present back up suit will be returned to the factory for reconditioning and alterations.

Test Equipment: One set of test equipment consisting of an integrator testor and power supply has been losned to the 4080th SRWg OL-19 to be used in testing flight equipment peculair to our aircraft. The test equipment will be returned upon completion of their TDY requirement.

O336 Faceplate: Pive (5) faceplates were losned to the 4080th SRWg temporarily under the same agreement as the losn of the test equipment.

CMU-1/P Ventilating Garments: Requisitions have been submitted along with SLOE change requests to obtain seven (7) additional ventilating garments. Testing of the garment in conjunction with our requirements reveal the garment will be of considerable help in cooling the pilots in sreas of high temperatures. See Research and Development for further comments.

In Flight Foods Hqs advised, 6 June our requirements for In-flight food tube had been ordered. To date we have not received the food and are at a point where there is only enough on hand to handle one prolonged staging. We are considering increasing our tube food requirements to support the dual staging concept plus provide for routine training flights at the home station.

STATINTL STATINTL

Supply Account:		has	signed	for	the	supply	account	prior	to
R1	ving the or	rgan	ization,	•					
Approved For F	2010250 200	2/06	/2A + CIA	-BDI	D75E	100326R	กกกวกกาก	าตักวร-ย	Ł

See L

7. Research and Development:

concerning the Q.D.

STATINTL

STATINTL

a. Hqs advised that a 35ft canopy parachute and a new	seat kit were	
being shipped to this station for evaluation in our progra	m. To date	
the equipment has not been received.		OT 4 TIV :-:
b. Q445 seat pack is presently at a stand still.	checke	STATINTL
into the Q.D. problem while at Laughlin.	reported	STATINTL
numerous malfunctions of the Q.D. had been experienced.	one happended	0
while was there. The Personal Equipment technic	cian checked	
the Q.D. for locing before and after the pilot hook-up and	d it checked	
out OK. The mobile officer double checked the Q.D. before	e closing canop	STATINTL
and it checked out OK. Then the pilot checked it and it	fell out arming	SIATINIL
the emergency oxygen bottle. In checking further with	the	
4080th Flying Safety Officer, and	I Was	STATINTL
advised that there were NO problems at all with the new Q	.D. and that th	6
discrepancies reported to the undersigned by	re not on recor	STATINIL
in the Flying Safety Office. The Flying Safety Officer h	ed nother but g	ood
comments concerning the Q.D. He did say he would look in	to the matter	STATINTL
the next time he got together with	was at Laughlin	
and was at Barksdale). Your attention is inv	ited to Persons	1
Equipment Report for February 1963, par 9a concerning LAC	's comments	

c. Portable Blower and CMU-1/P Ventilating Garment: Three (3)
tests were accomplished utilizing a 28Volt blower motor and a CMU-1/P
Ventilating garment to determine feasibility of providing air circulation
for pilots during transfer of pilot to aircraft and for time while in
aircraft up until closing of canopy. The tests went as follows:

Approved For Release 2002/06/24: CIA-RDP75B00326R000200100023-8

First Test: With CMU-1/P Ventilating garment and portable walk around bottles only. The garment provided sufficient circulation around the torso area when the regulator setting was on "emergency". Oxygen consumption was extremely high, however, and the bottles had to be recharged about ever 2 - 3 minutes. This is considered not practical for field use due to the limited supply of available oxygen. Second Tests This test was made with the aforementioned ventilating

garment, a small 28 V ambient air circulating blower, and the P.E. truck as a power source. The blower worked satisfactorily but a shielded wire was being used and it overheated and the test had to be terminated. Third Tests This test was the same as number two (2) except a new wire was used. And it was used on the pilot after he landed. The test was satisfactory. We are currently looking for utilization of the blower with an electrical source direct from the aircraft. This is being considered due to the different adapters required for utilization with the starting pod, the jeep startes, and the MA-2 Start Cart. proposed using an electrical Q.D. that fits the aircraft fan receptacle. A Q.D. is in the process of being obtained and this method will be

STATINT

checked out as soon as possible. 6. Personnels The unit is going to be definitely short of technically qualified Personnel in the forsecable future. will be will be due for release. leaving for discharge

STATINT

STATINT

just four (4) months therefrom the project in May 64, and

STATINT

after. The minimum manning for support of a dual staging concept is going to be affected starting the month of August, and in the event of sickness on the part of one of the remaining technicians, definitely imparized. Training: The current job profile for the 922 (Personal Approved For Release 2002/06/24: CIA-RDP75B00326R000200100023-8

COBA

Yess

XERO YERO

Equipment) career field with a suffix "B" indicates the individual must be school trained in the use and maintenance of the full pressure suit before the "B" can be awarded. Neigher of the P.E. technicians in this section have been thus trained and should be ASAP in order that the technicians might become current in their specialty.

STATINTL

NCOIC Personal Equipment